


# Liberty Rear Anti-Tip



If retrofitting, Anti-Tip Receivers will be needed.

Item Number	Part Number	Description	Quantity
1	003332	Receiver, Anti-Tip	1
2a	119676	Anti-Tip Assembly, 12", Liberty / Arc <i>Replaces 004076</i>	1
2b	119677	Anti-Tip Assembly, 16", Liberty / Arc <i>Replaces 004077</i>	1
2c	119678	Anti-Tip Assembly, 20", Liberty / Arc <i>Replaces 004078</i>	1
2d	119679	Anti-Tip Assembly, 22-24", Liberty, Arc, Cr45 <i>Comes pre-assembled as entire lower.</i>	1
3	101823	M6 X 20 Hhcs Blk Zn	1
4	101835	M6 Lock Washer Blk Zn	1