


Focus CR Rear Anti-Tip



| CONFIGURATION | QTY 101830 | QTY 101831 | QTY 101832 | QTY 102384 | |
|-------------------------|---------------|---------------|---------------|---------------|--|
| VENT TRAY | 4 | - | - | - 1 | |
| CABLE TILT | 22 | 4 | 82 | 270 | |
| FOOT TILT | | 2 | 2 | - | |
| CABLE TILT W/ FOOT LOCK | | (-) | 4 | (+) | |
| FOOT TILT W/ FOOT LOCK | - | | 2 | 2 | |

Anti-Tip assemblies are based on rear wheel size. Anti-Tip Receivers are installed on Focus chairs. Receivers are not needed when retrofitting anti-tips to a chair unless removing the Vent Tray and replacing the Vent Tray Anti-tips with the Focus CR Rear Anti-tips.

| Item Number | Part Number | Description | Quantity |
|-------------|-------------|-------------------------------------|----------|
| 1, 3, 7 | 501483 | Anti-Tip Assembly 12-16" Each Tilt | 1 |
| 1, 3, 7 | 501484 | Anti-Tip Assembly 20-22" Each Tilt | 1 |
| 1, 3, 7 | 501485 | Anti-Tip Assembly 24" Each Tilt | 1 |
| 1, 3, 7 | 501135 | Anti-Tip Assembly 12-16" Pair Focus | 1 |
| 1, 3, 7 | 501136 | Anti-Tip Assembly 20-22" Pair Focus | 1 |
| 1, 3, 7 | 501137 | Anti-Tip Assembly 24" Pair Focus | 1 |
| 2 | 001413 | Receiver Anti-Tip Long Tilt | 1 |

| Item Number | Part Number | Description | Quantity |
|-------------|-------------|---|----------|
| 3 | 100533 | Detent Button | 1 |
| 4a | 101831 | M8 x 80 HHCS Blk Zn Used if chair has hand tilt but foot lock is not used. | 2 |
| 4b | 101832 | M8 x 90 HHCS Blk Zn Used if chair has hand tilt and foot lock. Used if chair has foot tilt but foot lock is not used. | 2 |
| 4c | 102384 | M8 x 100 HHCS Blk Zc Part THD Used if chair has foot tilt and foot lock. | 2 |
| 5 | 100659 | M8 Nylock Nut Blk Zn | 2 |
| 6 | 101858 | Washer Flat M8 Blk Zn | 4 |
| 7 | 001170 | Anti-Tip Lower Extension Assembly, Focus | 1 |