


Catalyst 5VX Anti-Tip Receiver



Please see the Catalyst 5VX Swing-In Anti-Tip page for Swing-In Anti-Tip replacements

| Item Number | Part Number | Description | Quantity | Retail |
|-------------|-------------|--|----------|---------|
| 1b | 004539 | Anti Tip Receiver, Catalyst <i>Used if chair has an invoice date after November 13, 2018. Replaced 000046</i> | 1 | \$14.65 |
| 2a | 101826 | M6 x 50 HHCS Blk Zn <i>Use quantity 2 per side if only Anti-Tips are present. Use quantity 1 per side if Transit and Anti-Tips are present</i> | 2 | \$2.10 |
| 2b | 100676 | M6 x 55 CLS10.9 DIN931 HHCS ZC <i>Use quantity 2 per side if Transit and Anti-Tip are present. Use quantity 1 per side if Swing Away Arm bracket, Transit, and Anti-Tip are present</i> | 2 | \$1.58 |
| 2c | 100677 | M6 x 60 CLS10.9 DIN931 HHCS ZC <i>Use quantity 2 per side if Transit, Anti-Tip and Swing Away Arm bracket are present</i> | 2 | \$1.58 |
| 3 | 100658 | M6 Nylock Nut Blk Zn | 2 | \$1.05 |