


Rigid Side Guard Receiver



Item Number	Part Number	Description	Quantity	Retail
1, 2, 3, 4	503141	Wide Side Guard Receiver Assembly Black Anodized Rigid	1	\$51.49
5 - 8	501330	Wide Side Guard Clamp Receiver Assembly Black Anodized Rigid	1	\$69.86
1	004442	Wide Side Guard Receiver 1-3/8" w/ Chamfer Black Anodized Rigid Replaced part number 001415. This design effective October 23rd, 2020	1	\$44.13
2	101125	M6 x 55 BTN SHCS BLKZC	1	\$2.10
3	100746	M6 Flat Washer Blk Zn	1	\$1.58
4	100658	M6 Nylock Nut Blk Zn	1	\$1.05
5	004443	Wide Side Guard Clamp Receiver 1-3/8" w/ Chamfer Black Anodized Rigid Replaced part number 001437. This design effective October 23rd, 2020	1	\$47.28
6	000554	Side Guard Clamp Rigid	1	\$20.47
7	101810	M6 x 35 SHCS BLK ZC	2	\$1.05
8	102326	Flat Washer ID .254" x OD .396" Thickness .047" Zinc	2	\$0.53