


Catalyst 4 Anti-Tip Receiver



| Item Number | Part Number | Description | Quantity |
|-------------|-------------|--|----------|
| 1b | 004539 | Anti Tip Receiver, Catalyst <i>Used if chair has an invoice date after November 13, 2018. Replaced 000046</i> | 1 |
| 2 | 002329 | Amputee Anti-Tip Spacer CAT <i>Used when Anti-Tips are present with Reverse Mount Offset Axle Bracket</i> | 1 |
| 3a | 101826 | M6 x 50 HHCS Blk Zn <i>Used when Amputee Anti-Tip Spacer is not present</i> | 2 |
| 3b | 100544 | M6 x 75 CLS 8.8 DIN931 HHCS ZC <i>Used with Amputee Anti-Tip Spacer</i> | 2 |
| 4 | 100658 | M6 Nylock Nut Blk Zn | 2 |
| 5 | 000056 | Saddle 1 1/8" <i>Only used with Amputee Anti-Tip Spacer</i> | 3 |