


Tsunami AL Camber Tube - Growth



Camber Tube based on seat width <p>

A new Camber Tube is required when changing the degree of camber by more than 2° <p>

If Wheelchair Drive Ready Option is present, replacement parts need to be processed through Alber USA

Item Number	Part Number	Description	Quantity	Retail
1a	500724	Camber Tube Rigid 14" Kit Black	1	\$173.01
1b	500725	Camber Tube Rigid 15" Kit Black	1	\$173.01
1c	500726	Camber Tube Rigid 16" Kit Black	1	\$173.01
1d	500727	Camber Tube Rigid 17" Kit Black	1	\$173.01
1e	500728	Camber Tube Rigid 18" Kit Black	1	\$173.01
1f	500729	Camber Tube Rigid 19" Kit Black	1	\$173.01
1g	500730	Camber Tube Rigid 20" Kit Black	1	\$173.01
1h	500731	Camber Tube Rigid 21" Kit Black	1	\$173.01
1i	500732	Camber Tube Rigid 22" Kit Black	1	\$173.01

Item Number	Part Number	Description	Quantity	Retail
2	100667	M6 x 12 BTN SHCS BLKZC w/Patch	4	\$1.55
3	000066	M6 x 27 Threaded Barrel	2	\$4.37